

Errors in Miller textbook (Second Edition)

Revision: 21Mar99

Your contributions to this list are welcome.

- On page 81, Figure 2-37: The A6 corresponds to an LDAA instruction with indexed X addressing. The \$A6 should be a \$27, the opcode for the BEQ instruction.
- Page 363 near middle of page:
 - The ASCII code for 5 in hex is \$35, not \$65 as it says in the text.